



January & February



INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM

TMP7

Source output low

Steerer supply not regulating

Controls Network

Switch failed in 11B

Human Error

Sextupole ramp rate

Setpoints wrong for AGS extraction

QLI

Beam Induced Quenches

(today during Gap Cleaning)

PS_RHIC

"node cards" 11:00

Yellow Main Dipole PS

Rf_RHIC

Common Cavity Trip at rebucket

RHIC-AGS Synchro – DSP code

Anode cooling water for YS3

Cryo


Lost rack communication

Elec RHIC


Power Dip

Alcove 11C breaker trip – knocked


off access controls



Run10 availability (75.9%)



February Failure Hours (> 1 hr)



Failure – “Top 10 List”

