




# February & March




# Run10 availability (77.1%)



# Run 10 (AuAu) -- Integrated Luminosity by week

■ Phenix      ■ STAR      ■ (lumi) hours at store



# INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM -- MARCH2010

- RF\_AGS**  
STA K → Bunch Merge problems  
Synchro – inconsistent bunches
- QLI**  
Undetermined source
- PPS\_RHIC**  
Y abort kikcker prefire →QLI
- Rf\_RHIC**  
BS2 trips – beam debunch  
BS2 drops @ rebucketting
- BLM\_pulls permit**  
4x
- Experiments**  
Phenix – East Carriage HV mainframe  
STAR- ps reset
- Network**  
9a-sw108 & 7a-sw40
- Controls**  
Acclin85 related problems
- CRYO\_RHIC**  
Power supply for 11Q6 plc → lead  
flow indication
- QuenchDetect**  
Node Card reset then  
11b-qd1 problems

