



# February & March



# INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM -- MARCH 2010

PS\_RHIC  
Node card 11:00

- PPS\_RHIC
- B\_abort kicker ps trip
- B\_abort kicer prefire
- CRYO\_RHIC
- Lead flow – 1) PLC ps
- 2) Flow controller
- QuenchDetect
- 11-qd1 QD fec problem
- Experiments
- P-HBD problem
- S- AC for TPC
- Controls Hdwr
- Cfe-7a-ps3
- ELEC
- Power dips
- Human Error
- Tune feedback not turned off during up sequence
- Ps adjustment @ store killed store
- Injector performance
- AtR transport poor
- PS\_Exp
- North Muon PS

16  
14  
12  
10  
8  
6  
4  
2  
0

