



# April & May



# INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM --MAY 2010

## Rf\_RHIC

Phase detector – spontaneous reset of cfe-4a-rfulm

Human Error – recovery from MD

## VAC\_RHIC

Leak at Y injection kicker

## Controls Hardware

“low res” card – Y power supply interface in 5c alcove


## Access Controls

10z1 ODH sensor

8z2 ODH sensor

9z1 ODH sensor

Administrative control requires replacement



# Run10 availability (82.3%)

