



April & May



INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM --MAY 2010

Cool A/C AGS

Rf MG chiller trips

Ps ATR

8 degree ps fan (cooling)

PS RHIC

B_qmain – QLI

Rf_RHIC

Spontaneous reset of timing fec
Inject into wrong bucket

PS_EXP

STAR East trim supply

Elec RHIC

Alcove 7c circuit breaker trip


Inst_AGS

F15 lxfmr – module

Human Error

Operator filling RHIC did not see
F15 failed – booster extraction

4/27/10/2 to 05/04/10/1
05/04/10/2 to 05/11/10/1
05/11/10/2 to 05/18/10/1
05/18/10/2 to 05/25/10/1



Run10 availability (82.5%)

