



Availability February-March Run12

last week availability 86% -- Run12 availability 86%



INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM MARCH 2011

HumanError

Recovery of B Mains after
Bi9-q89 replaced
Reduced emittance in AGS
caused problems in RHIC

LM_PullsPermit

9 events

QLI

3 beam induced quenches

PS_RHIC

Bi9-q89ps replaced
Yi2-qd2 buffer card replaced

AtR_PS

Xarc90ps

Rf_RHIC

BS1 trips – pulls beam permit

PPS_RHIC

Y abort prefire – quench
Replaced trigger module

Experiments

BLIP inspection, short
STAR & PHENIX access

