

# CeC PoP Experiment

February 1, 2022

# CeC Operation

- Alignment of IR optics on bolometer was adjusted
- Cathode was changed during maintenance day but we experienced significant problems with gun. Attempts to condition it were unsuccessful.
- On Monday we withdraw the cathode from the gun and found that two RF fingers are missing. We need to remove the long manipulator and replace end effector (3-4 weeks).
- We continue gun conditioning

