



March & April



INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM --APRIL 2010

AccessControls

Logic Update after BS2 replaced

PS_RHIC

Bq_main – flattop at wrong time

Human Error


Incorrect mode switch procedure

Controls Hardware

Reboot

Cfe-2a-bbq1

Cfe-4b-ps1



Run10 availability (80.5%)

