



Availability February-March Run12

last week (24) availability 70% v 81% for week 23



INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM MARCH 2011

HumanError

Abort kicker timing
 Tech at STAR –CA key not captured
 PS settings in sequence; ramp->FT
 Rotator PS settings – quench

PS_RHIC

B8-q89ps
 B2-dh0

Rf_RHIC

9MHz bad cable – grid V sampled

PPS_RHIC

Abort kicker strength

Quench Protect

1010A QP switch failed
 B8-dhx-qp IGBTs shorted

