




# Availability February- March Run13

last week availability 70% previous week 83%



# Run13 availability <82%>



# INTEGRATED FAILURES (GREATER THAN ONE HOUR) BY SYSTEM MARCH 2013

**Rf\_AGS**

Problems with feedback amplifiers

**PS\_RHIC**

Rotator PS, bi4-tq5, yi6-tq4

**PPS\_RHIC**

B Inj kicker tripped – could not be turned on

**RF\_RHIC**

Fine tuning 9 MHz bouncers

**Controls Hd RHIC**

Problem with V124 module for BBQ

**Human Error**

Lost sweep, breakers opened on MCR UPS panel

**RHIC performance**

Saturday morning multiple permit pulls by snake

loss monitor – undiagnosed

**Experiments**

Jet target

**BLM pulls permit**

10x

**Quench Protect**

Bad connection for b8-dh0-qp controller

02/26/13/2 to 03/05/13/1  
 03/05/13/2 to 03/12/13/1  
 03/12/13/2 to 03/19/13/1  
 03/19/13/2 to 03/26/13/1

