

CeC PoP Experiment

January 4, 2022

CeC Operation

- We continue to setting up the electron beam in the diagnostics beamline
- We measured solenoids position and found that we have significant difference from the previous measurements for solenoids 2 and 3 – need to investigate
- Cathode QE is 1.0%. QE map is not uniform – the region with flat distribution is shifted by 1 mm

